## BUILDING SAFETY CERTIFICATE

137/ Technica/2024 25

Dated: 28/03/2025

It is certified that the existing building Gurukul School Dhamnod (name of the building or premises) at Maheshwar Road Dhamnod (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block	Block	Block	Block	Block	Block
	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	G+02	G + 02	G + 02			

The building is owned/occupied by. Late Shri Gokuldasji Bhandari Educational & Social Welfare Society (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD Sub Engineer in Manawar (Name of Department/ Govt.) on. 2.813.12025. (date of inspection) in the presence of Mrs Shilpa Sharma Principal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from . 2.81.3. [205] for a period of .27/831.2025. years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. Plovery good condition 2. roof -11-
- walls & plata h
- All amonitions

Issued on 2810312025 at by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail. RIDES --

Signature with Seal Divisional Officer Nam(B/R) Sub Division Manawar Dist.Dhar (M.P.)

Designation:

Name & Address of Department/ Office: